



Versandanschrift  
 Address  
 Adresse du destinataire  
 Indirizzo di trasporto  
 Dirección de expedición

---



---



---



---

Fax.-No

---

	30°	37.5°	45°	
<b>Ersatzteilliste</b>	0977694	0977695	0977696	<b>D 230V 50/60Hz</b>
<b>Spare parts list</b>	0977611	0977692	0977693	<b>CH 230V 50/60Hz</b>
<b>Liste des pièces de rechange</b>	0977697	0977698	0977699	<b>GB 110V 50Hz</b>
<b>Elenco parti di ricambio</b>	0977706	0977707	0977708	<b>USA 120V 50/60Hz</b>
<b>Lista de piezas de repuesto</b>	0977703	0977704	0977705	<b>PL 230V 50/60Hz</b>
	0977700	0977701	0977702	<b>KR 220V 60Hz</b>

**TruTool  
 TKF 700  
 (1A1)**

NO.	D'ORDINE NO. DE REF. NO. DE REF. ORDER. NO.	PEZZO DI RICAMBIO PIEZA DE RECAMBIO PIECE DE RECHANGE SPARE PART	QUAN. CANT. QUAN. QUAN.
NO	BEST.-NR.	ERSATZTEIL	DIN
1	0974652		
2	0751869	3M6x14	DIN 6325
3	0094676		
4	0131182		
5	0093539		
6	0113038		
7	0131188		
8	0130869		
9	0109924		
10	0134671		
11	0018350	M8x20-8.8	DIN 7991
14	0130881		
15	0132728	45°: 2x	
16	0131214		
17	0130882		
18	0134609	30°	
	0259379	37.5°	
	0977765	45°	
19	0131217		
21	0131061		
22	0131183		
23	0375702		
24	0134607	30°	
	0259380	37.5°	
	0977768	45°	
25	0131216		
26	0130871		

27	0131063		
28	0140807		
29	0136279	30°	
	0259385	37.5°	
	0131186	45°	
30	0130879		
	0130880		
31	0130878		
32	0131062		
33	0094666		
34	0094669		
35	0094667		
36	0085111		
37	0993851		
38	0094676		
39	0359353	M5X25	DIN 7500
40	0963618		
41	1265591	USA	
42	0976257	D 230V 50/60Hz	
	0976257	CH 230V 50/60Hz	
	0976254	GB 110V 50Hz	
	0976255	USA 120V 50/60Hz	
	0976257	PL 230V 50/60Hz	
	0976256	KR 220V 60Hz	
43	0347722	D 230V 50/60Hz	
	0347723	CH 230V 50/60Hz	
	0963653	GB 110V 50Hz	
	0347724	USA 120V 50/60Hz	
	0347722	PL 230V 50/60Hz	
0347722	KR 220V 60Hz		

